

Federal Energy Act Report

October 1, 2013 thru September 30, 2014

(Public Record Posted Date: October 22, 2014)

General Information:

Total Number of Active UST Facilities: **7,035**
Total Number of Active/Inactive USTs: **20,022**

Summary Information For On-Site Inspections:

Number of UST Facilities Inspected: **3,445**
Percent of UST Facilities in SOC Compliance: **63**

Summary Information For Releases:

Number of Confirmed UST Releases: **348**

Sources and Causes of Environmental Releases from Underground Storage Tanks in Illinois

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	139	39.9	0	0	2	0.6	5	1.4	80	23	0	0	0	0	52	14.9
Piping	24	6.9	0	0	0	0	2	0.6	11	3.2	0	0	0	0	11	3.2
Dispenser	2	0.6	0	0	0	0	0	0	0	0	0	0	0	0	2	0.6
Submersible (STP)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Delivery Problem	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Unknown	183	52.6	0	0	0	0	0	0	0	0	0	0	0	0	183	52.6
Other	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Totals	348	100	0	0	2	0.6	7	2	91	26.1	0	0	0	0	248	71.3

(source of data: Illinois Environmental Protection Agency)

To view site specific information at the Office of the State Fire Marshal, please visit: <http://webapps.sfm.illinois.gov/ustsearch/>

To view the LUST Incident Tracking Database, please visit: <http://epadata.epa.state.il.us/land/ust/Search.asp>

Revised 12/17/14